

TEP  
North Bank A  
Location # 336016



Battery signage



Separators





TEP  
North Bank A  
Location # 336016



**Tank battery**



**Well heads**





TEP  
North Bank A  
Location # 336016



**Pig station**



**Open cellars and staining under valves**





TEP  
North Bank A  
Location # 336016



Open cellars



Open cellars



TEP  
North Bank A  
Location # 336016



Debris



Stored equipment



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



TEP  
North Bank A  
Location # 336016



**Stored equipment from last inspection document #  
700704665**



**Recent inspection of stored equipment**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



TEP  
North Bank A  
Location # 336016



Disconnected lines to stored equipment from last inspections document # 700704665



Recent inspection of disconnected lines to stored equipment

TEP  
North Bank A  
Location # 336016



**Stored equipment from 2 inspections ago document # 700704160**



**Disconnected lines to stored equipment from 2 inspections ago document # 700704160**

