

Inspection Photos
Location Name: CAERUS PICEANCE LLC 012 Pad
Location #: 334650



Photo # 5 From entrance to location

Photo # 6 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC 012 Pad
Location #: 334650



Photo # 7 Location



Photo # 8 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC 012 Pad
Location #: 334650



Jun 9, 2023 at 11:05:55 AM
CO



Jun 9, 2023 at 11:06:13 AM
CO

Photo # 9 Location

Photo # 10 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC 012 Pad
Location #: 334650



Photo # 11 Debris



Photo # 12 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC 012 Pad
Location #: 334650



Photo # 16 Flowline heating insulation open ended

Photo # 20 wire/wildlife hazard

Inspection Photos
Location Name: CAERUS PICEANCE LLC 012 Pad
Location #: 334650



Photo # 22 wire/wildlife hazard