

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE N. PARACHUTE MIDDLE FORK NO4 696 Pad
Location #: 335598



**Location Overview: Location is approximately 573 yards from
Parachute Creek
Section/Township/Range: 4 6S96W**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE N. PARACHUTE MIDDLE FORK NO4 696 Pad
Location #: 335598



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control

Location Name: CAERUS PICEANCE N. PARACHUTE MIDDLE FORK NO4 696 Pad

Location #: 335598



**Photo # 9827 Transport of sediment onto location/
insufficient run on controls/BMP's**



**Photo # 9828 Transport of sediment onto location/
insufficient run on controls/BMP's**

Storm water Management and Erosion control

Location Name: CAERUS PICEANCE N. PARACHUTE MIDDLE FORK NO4 696 Pad

Location #: 335598



**Photo # 9831 Transport of sediment onto location/
insufficient run on controls/BMP's**



**Photo # 9841 Transport of sediment onto location/
insufficient run on controls/BMP's**

Storm water Management and Erosion control

Location Name: CAERUS PICEANCE N. PARACHUTE MIDDLE FORK NO4 696 Pad

Location #: 335598



**Photo # 9842 Transport of sediment onto location/
insufficient run on controls/BMP's**



**Photo # 9843 Transport of sediment onto location/
insufficient run on controls/BMP's**

Storm water Management and Erosion control

Location Name: CAERUS PICEANCE N. PARACHUTE MIDDLE FORK NO4 696 Pad

Location #: 335598



**Photo # 9844 Transport of sediment onto location/
insufficient run on controls/BMP's**



Photo # 9838 Lack of stabilization on cut slope

Storm water Management and Erosion control

Location Name: CAERUS PICEANCE N. PARACHUTE MIDDLE FORK NO4 696 Pad

Location #: 335598



Photo # 9839 Lack of stabilization on cut slope



Photo # 9846 Sediment trap needs maintenance

Storm water Management and Erosion control

Location Name: CAERUS PICEANCE N. PARACHUTE MIDDLE FORK NO4 696 Pad

Location #: 335598



Photo # 9847 Sediment trap needs maintenance