

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 104 Pad

Location ID: 322416

Jun 7, 2023 at 9:50:37 AM
CO



Photo # 9676 From entrance to location

Jun 7, 2023 at 9:51:15 AM
CO



Photo # 9677 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 104 Pad

Location ID: 322416



Photo # 9678 Location



Photo # 5693 From Inspection 708900299 conducted on 04/18/2023 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 104 Pad

Location ID: 322416



Photo # 9679 Meter calibration info not conspicuously posted



Photo # 9680 Meter calibration info not conspicuously posted