

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

02/09/2023

Document Number:

403317099

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: <u>17320</u>	Contact Person: <u>Emma Millar</u>
Company Name: <u>CITY & COUNTY OF DENVER</u>	Phone: <u>(208) 610-6012</u>
Address: <u>8500 PENA BLVD AOB 10TH FLOOR</u>	Fax: <u>()</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80249-6340</u>	Email: <u>emillar@cottonwoodconsulting.com</u>

Identification Information

API Number: <u>05 - 001-06892</u>	OGCC Facility ID: <u>201489</u>	Initial Form 19 or 27 Document number: <u>403153411</u>
Facility Name: <u>CHAMPLIN 117 AMOCO C</u>	Facility Number: <u>5</u>	Facility Type: <u>WELL</u>
Location QtrQtr: <u>NESW</u>	Section: <u>1</u>	Township: <u>2S</u>
	County: <u>ADAMS</u>	Range: <u>66W</u>
		Meridian: <u></u>
		Field Name: <u>THIRD CREEK</u>
Federal, Indian or State Lease Number: <u></u>		

Information Submitted By:

Company Name: <u>CITY & COUNTY OF DENVER</u>	Agent Name: <u>Emma Millar</u>	Title: <u>Consultant</u>
Phone Number: <u>208-610-6012</u>	Email: <u>emillar@cottonwoodconsulting.com</u>	

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: <u>201489</u>	Facility Name: <u>CHAMPLIN 117 AMOCO C 5</u>	Facility Type: <u></u>
Location: QtrQtr: <u>NESW</u>	Sec: <u>1</u>	Twp: <u>2S</u>
	Range: <u>66W</u>	Meridian: <u>6</u>
County Name: <u>ADAMS</u>	Latitude: <u>39.905280</u>	Longitude: <u>-104.726690</u>

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: <u>107684</u>	Document Name: <u>Size of file in bytes: 98816</u>	File Name: <u>Champlin 117 Amoco C #5 Soil Sample EDD (1).xls</u>
SampleType: <u></u>	Matrix: <u></u>	
Facility ID: <u>201489</u>	Sample ID: <u>646123</u>	Sample Name: <u>Champlin 117 Amoco C #5</u>
		Sample Date: <u>11/01/2022</u>
Collection Point: <u>WellHead</u>	Matrix: <u>SOIL</u>	Pre Post: <u>Remediation</u>
Project Number: <u></u>	Remediation Number: <u>25370</u>	Complaint Number: <u></u>
		NOAV Number: <u></u>
Inspection Number: <u></u>	Spill Number: <u></u>	Laboratory: <u>Green Analytical Laboratories, Inc.</u>
		Lab Sample ID: <u>2211019-01</u>

Batch ID: 107685 Document Name: Size of file in bytes: 98816 File Name: Champlin 117 Amoco C #5 Soil Sample EDD (2).xls

SampleType: _____ Matrix: _____

Facility ID: 201489 Sample ID: 646124 Sample Name: Champlin 117 Amoco C #5 Sample Date: 11/01/2022

Collection Point: PRODEQP Matrix: SOIL Pre Post: Production Gas Sample

Project Number: _____ Remediation Number: 25370 Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2211019-02

Sample Facility Attachment:

No Facility Attachment

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	The data submitted by the operator can be accessed through the COGIS data system.	06/13/2023
Total: 1 comment(s)		