

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	iron		
Corrective Action:		Date:	

Equipment:

Type:			corrective date
Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:	it appears gas meter is not annually calibrated. See attached photo.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	06/30/2023
Emission Control Device	# 2		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities					
Facility ID:	425377	Type:	WELL	API Number:	123-34361
		Status:	TA	Insp. Status:	TA
Idle Well					
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: PREVIOUS INSPECTION		
Comment:	<input style="width: 90%;" type="text"/>				
Corrective Action:	<input style="width: 90%;" type="text"/>				Date: <input style="width: 10%;" type="text"/>
Facility ID:	425381	Type:	WELL	API Number:	123-34364
		Status:	SI	Insp. Status:	SI
Idle Well					
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: EQUIPMENT ONSITE		
Comment:	<input style="width: 90%;" type="text"/>				
Corrective Action:	<input style="width: 90%;" type="text"/>				Date: <input style="width: 10%;" type="text"/>
Facility ID:	425382	Type:	WELL	API Number:	123-34365
		Status:	TA	Insp. Status:	TA
Idle Well					
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: EQUIPMENT PRESENT/DISCONNECTED		
Comment:	<input style="width: 90%;" type="text"/>				
Corrective Action:	<input style="width: 90%;" type="text"/>				Date: <input style="width: 10%;" type="text"/>
Facility ID:	425383	Type:	WELL	API Number:	123-34366
		Status:	TA	Insp. Status:	TA
Idle Well					
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: EQUIPMENT PRESENT/DISCONNECTED		
Comment:	<input style="width: 90%;" type="text"/>				
Corrective Action:	<input style="width: 90%;" type="text"/>				Date: <input style="width: 10%;" type="text"/>
Facility ID:	425384	Type:	WELL	API Number:	123-34367
		Status:	TA	Insp. Status:	TA
Idle Well					
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: EQUIPMENT PRESENT/DISCONNECTED		
Comment:	<input style="width: 90%;" type="text"/>				
Corrective Action:	<input style="width: 90%;" type="text"/>				Date: <input style="width: 10%;" type="text"/>
Facility ID:	425394	Type:	WELL	API Number:	123-34371
		Status:	PR	Insp. Status:	SI
Idle Well					
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: EQUIPMENT ONSITE		
Comment:	<input style="width: 90%;" type="text"/>				
Corrective Action:	<input style="width: 90%;" type="text"/>				Date: <input style="width: 10%;" type="text"/>
Facility ID:	425396	Type:	WELL	API Number:	123-34373
		Status:	TA	Insp. Status:	TA

Idle Well

Purpose: Shut In

Temporarily Abandoned

Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679605165. All previous corrective actions have been resolved. One new corrective action was observed at the time of re-inspection. Please review narrative below for additional information on this location.</p> <p>COGCC Inspection Report Summary **Weather Conditions: SUNNY, DRY GROUND On Tuesday, June 6, 2023 at approximately 1330, I, Inspector Brittani Santistevan, conducted an on-site inspection at BOOTH USX EE25-11D (Noble Energy Inc), at location #: 425393 in WELD COUNTY Colorado. While there, I observed a shut in facility. During this inspection the following possible compliance issues were observed: 1. It appears the gas meter is not annually calibrated. Calibrate gas metering equipment annually to comply with rule 430.d.(1). (Corrective Action Date: June 30, 2023) See attached photo #4. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	06/06/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403425932	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6138455
679605673	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6138447