

Operator: HIGHPOINT OPERATING CORPORATION
Location Name: Anschutz State 5-62-27_34 SESE 22
Loc ID: 421665
Inspection: 696304978



Exhibit A



Exhibit B



Exhibit C

CA: Stained Soil at 4-22 Gas Engine and Exhaust. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

CA Resolution: Stained soil identified around the Gas Engine and Exhaust has been appropriately cleaned and disposed of to comply with Rule 905.e.



Exhibit A



Exhibit B

CA: Unused Wellhead Parts at 4-22; See photos. Comply with Rule 606.

CA Resolution: Unused parts/equipment have been addressed and removed. Location has been cleared/cleaned of any trash and debris to comply with Rule 606.