

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB-TG LAND Pad

Location #: 418555



Photo # 630 From entrance to location



Photo # 631 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB-TG LAND Pad

Location #: 418555



Photo # 633 Location



Photo # 634 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB-TG LAND Pad

Location #: 418555



Photo # 632 Location



Photo # 635 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB-TG LAND Pad

Location #: 418555



Photo # 636 Methanol tank missing required information



Photo # 637 Methanol tank missing required information



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB-TG LAND Pad

Location #: 418555



Photo # 638 Meter calibration info not conspicuously posted



Photo # 639 Meter calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB-TG LAND Pad

Location #: 418555



Photo # 640 Meter calibration info not conspicuously posted



Photo # 641 Meter calibration info not conspicuously posted



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB-TG LAND Pad

Location #: 418555



Photo # 649 Debris



Photo # 650 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB-TG LAND Pad

Location #: 418555



Photo # 651 Debris



Photo # 672 Unmarked deadman