

Inspection Photos

API: 067-06558

Operator: BP AMERICA PRODUCTION
COMPANY

Inspection Date: 6/14/2023



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 325529 | Date: 6/14/2023

Inspection Photos



Photo 1. Facing southeast toward the plugged and abandoned wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 325529 | Date: 6/14/2023

Inspection Photos



Photo 2. There are noxious weeds at the location that need to be controlled. Red arrow points to Musk thistle.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 325529 | Date: 6/14/2023

Inspection Photos



Photo 3. There are noxious weeds at the location that need to be controlled. Red arrow points to Mullein.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 325529 | Date: 6/14/2023

Inspection Photos



Photo 4. Southeast side of the location facing southwest. There are numerous wooden stakes from wattle BMP's that need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 325529 | Date: 6/14/2023

Inspection Photos



Photo 5. Southwest side of the location facing northeast. This area has not established vegetation and needs to be reseeded. Approximate area 80'x60'.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 325529 | Date: 6/14/2023