

Inspection Photos

Location Name: Irwin 6-65 23-11 10HN

Location ID: 479194

Jun 14, 2023 at 2:51:37 PM
39.508309,-104.625659
Elbert County
COGCC



Pic 1 entrance to location

Jun 14, 2023 at 2:52:19 PM
39.509659,-104.625520
Elbert County
COGCC



Pic 2 Electrical equipment

Inspection Photos

Location Name: Irwin 6-65 23-11 10HN

Location ID: 479194

Jun 14, 2023 at 2:52:46 PM
39.509941,-104.625511
Elbert County
COGCC



Pic 3 wellhead, no wellhead sign observed on wellhead

Jun 14, 2023 at 2:53:38 PM
39.510036,-104.625563
Elbert County
COGCC



Pic 4 Separator, GMR

Inspection Photos

Location Name: Irwin 6-65 23-11 10HN

Location ID: 479194

Jun 14, 2023 at 2:53:53 PM
39.510036,-104.625563
Elbert County
COGCC



Pic 5 Generator / electrical equipment

Jun 14, 2023 at 2:54:02 PM
39.510036,-104.625563
Elbert County
COGCC



Pic 6 ECD

Inspection Photos

Location Name: Irwin 6-65 23-11 10HN

Location ID: 479194

Jun 14, 2023 at 2:54:11 PM
39.509972,-104.625448
Elbert County
COGCC



Pic 7 VRT, VRU, tanks

Jun 14, 2023 at 2:54:20 PM
39.509972,-104.625448
Elbert County
COGCC



Pic 8 location BMP appear to be failing to control storm water.