

Inspection Photos
Location Name: Crystal 6-65 22-10 10HN
Location ID: 479191



Pic 1 entrance to location, BMP failure, stormwater erosion on locaiton



Pic 2 tanks, BMP failure on location, stormwater mitigation failure.

Inspection Photos
Location Name: Crystal 6-65 22-10 10HN
Location ID: 479191



Pic 3 tanks



Pic 4 ECD, Separator, GMR, VRU, natural gas generator.

Inspection Photos

Location Name: Crystal 6-65 22-10 10HN

Location ID: 479191

Jun 14, 2023 at 3:04:05 PM
39.511354,-104.645502
Elbert County
COGCC



Pic 5 compressor, electric / automation.

Jun 14, 2023 at 3:04:14 PM
39.511469,-104.645464
Elbert County
COGCC



Pic 6 stormwater BMP has vailed on location.

Inspection Photos
Location Name: Crystal 6-65 22-10 10HN
Location ID: 479191



Pic 7 wellhead sign not visible during inspection.



Pic 8 stormwater BMP failure

Inspection Photos
Location Name: Crystal 6-65 22-10 10HN
Location ID: 479191



Pic 9, stormwater on location



Pic 10 stormwater on location.