

Inspection Photos
Location Name: State 16-3-61-1H
Location ID: 427445



Photo 1 – ECD



Photo 2 – Tank Battery

Inspection Photos
Location Name: State 16-3-61-1H
Location ID: 427445



Photo 3 – Stained Soil



Photo 4 – Casing Gauge

Inspection Photos
Location Name: State 16-3-61-1H
Location ID: 427445



Photo 5 – Tank Battery Sign

Photo 6 – Heater Treater

Inspection Photos
Location Name: State 16-3-61-1H
Location ID: 427445



Photo 7 – Propane Tank



Photo 8 – Flare

Inspection Photos
Location Name: State 16-3-61-1H
Location ID: 427445



Photo 9 – Stained Soil



Photo 10 – Pumping Unit has been removed – Stained Soil remains

Inspection Photos
Location Name: State 16-3-61-1H
Location ID: 427445



Photo 11 – Stained Soil



Photo 12 – Unmark Riser

Inspection Photos
Location Name: State 16-3-61-1H
Location ID: 427445



Photo 13 – Stained Soil East of Wellhead

Photo 14 – Stained Soil East of Wellhead

Inspection Photos
Location Name: State 16-3-61-1H
Location ID: 427445




Photo 15 – Stained Soil at Wellhead



Photo 16 – Stained Soil at Wellhead

Inspection Photos
Location Name: State 16-3-61-1H
Location ID: 427445



Photo 17 – Stained Soil East of Wellhead



Photo 18 – Latrine knocked over