

## Inspection Photos

Location Name: CAERUS PICEANCE LLC C29NE 692 Pad

Location #: 335361



Photo # 1198 From entrance to location



Photo # 1199 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC C29NE 692 Pad

Location #: 335361



Photo # 1200 Location



Photo # 1201 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: CAERUS PICEANCE LLC C29NE 692 Pad

Location #: 335361



Photo # 1211 Stained gravel in secondary containment



Photo # 1212 Stained gravel in secondary containment