

Inspection Photos

API: 067-08707

Operator: SIMCOE LLC

Inspection Date: 6/15/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 067-08707 | Date: 6/15/2023

Inspection Photos



Photo 1. Facing northwest toward the location. There are numerous noxious weeds at the location that need to be controlled. Red arrow points to Musk thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 067-08707 | Date: 6/15/2023

Inspection Photos



Photo 2. Facing southwest at the location. There are numerous noxious weeds at the location that need to be controlled. Red arrow points to Musk thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 067-08707 | Date: 6/15/2023