

Inspection Photos
Location Name: UPRR 42 Pan AM D 2
Location ID: 318931



Photo 1 WH sign.



Photo 2 WH.

Inspection Photos
Location Name: UPRR 42 Pan AM D 2
Location ID: 318931



Photo 3 Pump Jack.

Photo 4 Ancillary equip..

Inspection Photos
Location Name: UPRR 42 Pan AM D 2
Location ID: 318931



Photo 5 TB sign.



Photo 6 TB

Inspection Photos
Location Name: UPRR 42 Pan AM D 2
Location ID: 318931



Photo 7 Spill on the east side of the East Crude tank.



Photo 8 Spill on the east side of the East Crude tank.

Inspection Photos
Location Name: UPRR 42 Pan AM D 2
Location ID: 318931



Photo 9 Spill on the east side of the East Crude tank.



Photo 10 Spill on the east side of the East Crude tank.

Inspection Photos
Location Name: UPRR 42 Pan AM D 2
Location ID: 318931



Photo 11 Crew cleaning spill with vacuum truck.



Photo 12 Free liquid removed from inside the berm.