

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/21/2023

Submitted Date:

06/23/2023

Document Number:

701007093

**FIELD INSPECTION FORM**
 Loc ID 321808 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 61250

Name of Operator: MULL DRILLING COMPANY INC

Address: 1700 N WATERFRONT PKWY B#1200

City: WICHITA State: KS Zip: 67206-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name   | Phone | Email                     | Comment                         |
|----------------|-------|---------------------------|---------------------------------|
| OBryhim, Reesa |       | ROBryhim@mulldrilling.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 208080      | WELL | PR     | 08/21/1990  | OW         | 017-07015 | SCHLUNTZ 3    | PR          |

**General Comment:**[Routine Inspection](#)

**Location**

|                    |                                 |       |  |
|--------------------|---------------------------------|-------|--|
| <b>Lease Road:</b> |                                 |       |  |
| Type               | Access                          |       |  |
| comment:           | Gravel road through farm ground |       |  |
| Corrective Action  | L                               | Date: |  |

Overall Good: ☒

|                      |                            |       |  |
|----------------------|----------------------------|-------|--|
| <b>Signs/Marker:</b> |                            |       |  |
| Type                 | TANK LABELS/PLACARDS       |       |  |
| Comment:             | Metal signs by tanks       |       |  |
| Corrective Action:   |                            | Date: |  |
| Type                 | BATTERY                    |       |  |
| Comment:             | Lease sign at tank battery |       |  |
| Corrective Action:   |                            | Date: |  |
| Type                 | WELLHEAD                   |       |  |
| Comment:             | Lease sign by unit         |       |  |
| Corrective Action:   |                            | Date: |  |

|                           |       |  |  |
|---------------------------|-------|--|--|
| Emergency Contact Number: |       |  |  |
| Comment:                  |       |  |  |
| Corrective Action:        |       |  |  |
|                           | Date: |  |  |

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |                                       |       |  |
|--------------------|---------------------------------------|-------|--|
| <b>Fencing/:</b>   |                                       |       |  |
| Type               | PUMP JACK                             |       |  |
| Comment:           | Metal panels around unit and wellhead |       |  |
| Corrective Action: |                                       | Date: |  |

|                           |   |       |                 |
|---------------------------|---|-------|-----------------|
| <b>Equipment:</b>         |   |       | corrective date |
| Type: Ancillary equipment | # 3   |       |                 |
| Comment:                  | Electric panel, cathodic rectifier, telemetry equipment |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Pump Jack           | # 1   |       |                 |
| Comment:                  | CMI 320   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: FWKO                | # 1   |       |                 |
| Comment:                  | FWKO on south side of location at tank battery          |       |                 |
| Corrective Action:        |   | Date: |                 |

|                    |                |       |
|--------------------|----------------|-------|
| Type: Prime Mover  | # 1            |       |
| Comment:           | Electric motor |       |
| Corrective Action: |                | Date: |

**Tanks and Berms:**

|                    |   |          |                |         |                       |
|--------------------|---|----------|----------------|---------|-----------------------|
| Contents           | #   | Capacity | Type           | Tank ID | SE GPS                |
| CRUDE OIL          | 2   | 300 BBLs | FIBERGLASS AST |         | 38.894940,-102.259270 |
| Comment:           | Central tank battery is 1365' SSE of wellhead |          |                |         |                       |
| Corrective Action: |   |          |                |         | Date:                 |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

| Inspected Facilities |   |       |      |             |           |         |    |               |    |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 208080  | Type: | WELL | API Number: | 017-07015 | Status: | PR | Insp. Status: | PR |
| Producing Well       |   |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Central tank battery 1365' SSE of wellhead @ 38.894940/-102.259270 |       |      |             |           |         |    |               |    |
| Corrective Action:   |   |       |      |             |           |         |    | Date:         |    |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT