

Inspection Photos

Location Name: BUCKCHERRY USX AA-66N63W/3NWSW

Location #: 302381



Colorado Oil & Gas Conservation Commission
Weld County
+40.513347, -104.429183
323° NW
2023-06-23 10:47



Colorado Oil & Gas Conservation Commission
Weld County
+40.513344, -104.428844
275° W
2023-06-23 10:48

Photo #1

Buckcherry USX AA 03-12 (123-29040) Wellsite

Plugged & Abandoned | PA

Plugging Ops: Cementing: Surface plug

Cement units

Witnessed good cmt in returns

Photo #2

Buckcherry USX AA 03-12 Wellsite

Plugged & Abandoned | PA

Plugging Ops: Cementing: Surface plug

Site safety signage

Inspection Photos

Location Name: BUCKCHERRY USX AA-66N63W/3NWSW
Location #: 302381




Photo #3
Buckcherry USX AA 03-12 (123-29040) Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: Surface plug
JSA: 2023-06-23



Photo #4
Buckcherry USX AA 03-12 Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: Surface plug
Wellsite entrance sign