

**PUBLIC SERVICE COMPANY OF COLORADO, CHRISTIANA-FED-  
69S101W/9SWSE  
Location #312362  
Date: 6/21/2023**



**NW Corner of Location – Photo #04657**

**SW Corner of Location – Photo #04658**

**PUBLIC SERVICE COMPANY OF COLORADO, CHRISTIANA-FED-  
69S101W/9SWSE  
Location #312362  
Date: 6/21/2023**



**East Entrance to Location – Photo #04659**

**Wellhead – Photo #04660**

**PUBLIC SERVICE COMPANY OF COLORADO, CHRISTIANA-FED-  
69S101W/9SWSE  
Location #312362  
Date: 6/21/2023**



**Separator/Dehydrator/Produced Water Tank –  
Photo #04665**



**Location Lacks Stabilization – Photo #04663**

**PUBLIC SERVICE COMPANY OF COLORADO, CHRISTIANA-FED-  
69S101W/9SWSE  
Location #312362  
Date: 6/21/2023**



**Location Lacks Stabilization – Photo #04668**



**Insufficient Vehicle Tracking BMPs at Location  
Entrance/Exit – Photo #04669**