

# PUBLIC SERVICE COMPANY OF COLORADO, FEDERAL-69S101W/13NWSW

Location #312597

Date: 6/21/2023



**NW Corner of Location – Photo #04695**

**NE Corner of Location – Photo #04696**

# PUBLIC SERVICE COMPANY OF COLORADO, FEDERAL-69S101W/13NWSW

Location #312597

Date: 6/21/2023



**SE Corner of Location – Photo #04697**

**SW Corner of Location – Photo #04698**

# PUBLIC SERVICE COMPANY OF COLORADO, FEDERAL-69S101W/13NWSW

Location #312597

Date: 6/21/2023



Wellhead – Photo #04702

Separator/Dehydrator/Produced Water Tank –  
Photo #04703

# PUBLIC SERVICE COMPANY OF COLORADO, FEDERAL-69S101W/13NWSW

Location #312597

Date: 6/21/2023



Unmarked Anchor – Photo #04699



Trash on Location – Photo #04701

# PUBLIC SERVICE COMPANY OF COLORADO, FEDERAL-69S101W/13NWSW

Location #312597

Date: 6/21/2023



**Debris on Location – Photo #04705**



**Sediment Trap Washed Out & Needs Maintenance –  
Photo #04700**

# PUBLIC SERVICE COMPANY OF COLORADO, FEDERAL-69S101W/13NWSW

Location #312597

Date: 6/21/2023



**Rill Erosion on Access Road/Rip Rap BMP Needs Maintenance – Photo #04706**

**Rip Rap BMP Needs Maintenance – Photo #04707**