

Final Reclamation Inspection

June 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 445225

Inspection Document #: 701900891

SWNW Section 17 T5N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Schaumburg 17G-214AB
Location ID: 445225



Photo 1. 2021 aerial imagery of the well pad (north is up). The tank battery (highlighted in blue) remains to service the producing wells on site. Note: rill erosion location.

Inspection Photos
Location Name: Schaumburg 17G-214AB
Location ID: 445225



Photo 2. Overview photo of the reclaimed well taken at ground level from the southern edge of the well looking north. Note: the reclaimed well sits between two producing wells on site.

Inspection Photos
Location Name: Schaumburg 17G-214AB
Location ID: 445225



Photo 3. Rill erosion located on south eastern edge of the tank battery.