

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location #311586

Date: 6/25/2023



SW Corner of Location – Photo #04808



SE Corner of Location – Photo #04809

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location #311586

Date: 6/25/2023



NW Corner of Location – Photo #04810



SE Corner of Location – Photo #04811

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location #311586

Date: 6/25/2023



Wellheads – Photo #04812



Separators – Photo #04813



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location #311586

Date: 6/25/2023



Tank Battery – Photo #04814



Location Lacks Stabilization – Photo #04815

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SENW

Location #311586

Date: 6/25/2023



Location Lacks Stabilization – Photo #04816



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #04818