

**Inspection Photos**  
**Location Name: Grotheer 1A**  
**Location ID: 454760**



**Photo 1 – Wellheads**



**Photo 2 – Separators**

**Inspection Photos**  
**Location Name: Grotheer 1A**  
**Location ID: 454760**



**Photo 3 – Gas Meter Injection House**



**Photo 4 – Instrumental Air Units**

**Inspection Photos**  
**Location Name: Grotheer 1A**  
**Location ID: 454760**



**Photo 5 – LACTs**



**Photo 6 – ECDs**

**Inspection Photos**  
**Location Name: Grotheer 1A**  
**Location ID: 454760**



**Photo 7 – Unused Building in NE Corner of Location**

**Photo 8 – Trash overflowing and NOT Covered**

**Inspection Photos**  
**Location Name: Grotheer 1A**  
**Location ID: 454760**



**Photo 9 – Maintenance Tank**