

# Interim and Stormwater Inspection

June 6, 2023

Operator: Verdad Resources # 10652

Location ID: 320197

Inspection Document #:709400297

Adams, County

SWSE, Section 18, 1S65W

Reed Wold

Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Tracey 1  
Location ID: 320197



Photo 1. Photo taken of Location sign.



Photo 2. photo of tank ba



Inspection Photos  
Location Name: Tracey 1  
Location ID: 320197



**Photo 3. Photo taken of concrete rubble on location .**



**Photo 4. Photo of erosion of access road and concrete rubble on site.**

Inspection Photos  
Location Name: Tracey 1  
Location ID: 320197



**Photo 5. Photo taken of weeds and cheatgrass on site.**

