

Interim and Stormwater Inspection

June 6, 2023

Operator: Extraction Oil & Gas# 10459

Location ID: 320612

Inspection Document #:709400303

Adams, County

NWSW, Section 30, 1S65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Wenzel 1
Location ID: 320612



Photo 1. Photo taken of Location sign.



Photo 2. Photo of tank battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 7094001303

Inspection Photos
Location Name: Wenzel 1
Location ID: 320612



Photo 3. Photo taken of unlabeled open tote on site. Berm around tanke battery is insufficient.



Photo 4. Photo of erosion on site from recent rains.

Inspection Photos
Location Name: Wenzel 1
Location ID: 320612



Photo 5. Photo taken of Weeds on location.



Photo 6. See photo 5 comments.