

# Inspection Photos

6/28/2023

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 420224

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location Number: 420224



**Photo 1:** Photo shows the new entrance on the east end of the Location. Photo also shows new gate installed.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 420224



**Photo 2:** Photo taken along the newly paved road. Photo shows a remaining portion of the O&G access road that travels southeast.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 420224



June 28, 2023



June 28, 2023

**Photo 3:** Photos 3-4 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east. Photos also show stormwater diversion ditch with gravel armoring on the south end of the Location.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location Number: 420224



**Photo 4:** See comments under photo 13.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location Number: 420224



**Photo 5:** Photos taken from the west end of the Location. Photo provides an overview of the Location from northeast to east.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 420224



**Photo 6:** Photo shows sediment trap and culvert on the southeast end of the Location. BMP tied to the stormwater ditch on the south end of the Location.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location Number: 420224



**Photo 7:** Vehicle tracking pad

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 420224



**Photo 8:** Stormwater diversion ditch and outlet on the north end of the Location. Photo right also example showing trash debris observed throughout the Location.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 420224



**Photo 9:** Armored inlet to manage run-on, on the north end of the Location.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 420224



**Photo 10:** Photo taken from the north end of the Location. Hydromulch on slopes no longer in proper functioning condition; erosion/degradation beginning to recur. Photo also shows Undesirable and Noxious Plant (Halogeton, kochia) establishment on slopes.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 420224



**Photo 11:** Photo taken from the north end of the Location. Hydromulch on slopes no longer in proper functioning condition; erosion/degradation beginning to recur. Photo also shows Undesirable and Noxious Plant (Halogeton, kochia) establishment on slopes.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 420224



**Photo 12:** Slopes on northwest end of the Location. Slopes appear to have been recently hydromulched. BMP appears to be in proper functioning condition.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 420224



**Photo 13:** Photos 13-14 examples showing trash debris observed throughout the Location.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location Number: 420224



**Photo 15:** See comments under photo 14.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location Number: 420224



**Photo 15:** Photo shows tank battery with required signage on the east end of the Location.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location Number: 420224



**Photo 16:** Photo shows tank battery on the west end of the Location. Signage required per Rule 605.e not observed at facility.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location Number: 420224



**Photo 17:** Labels at methanol tanks becoming illegible. Maintenance advised.