

Inspection Photos

6/28/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 467272

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 467272



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 467272



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 467272



Photo 3: Photos 3-4 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest to north.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 467272



Photo 4: See comments under photo 3.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 467272



Photo 5: Unused Tanks/containers stored on the southeast end of the Location. Tanks missing required labeling.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 467272



Photo 6: Pipe, cellar cover improperly stored on the southeast end of the Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 467272



Photo 7: Unused pipe behind separators.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 467272





Photo 8: Wells missing required signage.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 467272



Photo 9: Tank battery facility missing required signage.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 467272



Photo 10: Soil stockpiles on Location missing BMPs per 1002.c

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 467272



June 28, 2023

Photo 11: Stockpile on southwest end of the Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 467272



Photo 12: Photo shows mobile heater equipment stored on Location. Equipment not necessary for production. Photo also example showing example stained soils observed around the heater, wellheads, and gas lift equipment currently active on the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 467272



Photo 13: Stained soils around battery and separator equipment.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 467272



Photo 14: Containment BMP at the Gas Lift equipment with fluids.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 467272



Photo 15: Photos 15-16 examples showing lines/pipe at and around the separator equipment not properly capped.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 467272




Photo 16: See comments under photo 15.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 467272



Photo 17: Photos examples showing areas where erosion logs appear to have been lifted during maintenance work, and placed back onto the surface. BMP has not been installed per good engineering practice (trenched/backfilled).

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 467272



Photo 18: Sediment trap and outlet on west end of the Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 467272



Photo 19: Photos examples showing erosion logs that have been compressed/flattened, and no longer in proper functioning condition.