

# Final Reclamation Inspection

May 31st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 332809

Inspection Document #: 701900902

NWSW Section 28 T5N R64W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Adamson 1-6I  
Location ID: 332809



**Photo 1.** 2021 aerial imagery of the well pad (north is up). The tank battery highlighted in blue remains in service for the temporarily abandoned well API #123-11998.



Inspection Photos  
Location Name: Adamson 1-6I  
Location ID: 332809



**Photo 2.** Overview photo of the reclaimed well taken at ground level from the northern edge looking south. Note: Producing well remains on site.



Inspection Photos  
Location Name: Adamson 1-6I  
Location ID: 332809



**Photo 3.** Rill erosion observed on the western edge of the tank battery has not been addressed since previous inspection form was submitted on November 16th, 2021.