

# Final Reclamation Inspection

May 31st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 323171

Inspection Document #: 701900938

NWSE Section 10 T4N R67W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Nadine 1-24  
Location ID: 323171



**Photo 1.** 2021 aerial imagery of the well pad and tank battery. Note: well pad falls within a commercial lot owned by Western Equipment Truck Inc.

Inspection Photos  
Location Name: Nadine 1-24  
Location ID: 323171



**Photo 2.** Overview photo of the well pad taken at ground level from the northern edge facing south. Note: well pad falls within a commercial area.

Inspection Photos  
Location Name: Nadine 1-24  
Location ID: 323171



**Photo 3.** Overview photo of the tank battery taken at ground level from the western edge facing east. Note: tank battery has been disturbed but has stormwater issues (rill erosion/pooling water) indicated by red arrows.