

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 1 Wellsite.

Photo 2 WH sign

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 3 Well site excavation.

Photo 4 Pump Jack partially disassembled.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 5 No BMPs installed, sediment is washing off the wellsite into the planted field towards the SE.

Photo 6 No BMPs installed, sediment is washing off the wellsite into the planted field towards the SE.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 7 No BMPs installed, sediment is running off the wellsite into the planted field towards the SE.



Photo 8 Flow line excavation looking to the battery, sediment is running off into the planted field.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 9 TB sign, excavation work in the background

Photo 10 Flow line excavation looking to the wellsite, sediment is running off into the planted field.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 11 TB location.

Photo 12 excavation work at the battery location.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 13 TB location excavation work.

Photo 14 excavation work at the battery location.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 15 vertical heater treater.

Photo 16 excavation work at the battery location.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 17 Dirt/Sediment washing off the road into the field by the TB location.

Photo 18 Dirt/Sediment washing off the road into the field by the TB location.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 19 Dirt/Sediment washing off the road into the field by the TB location.

Photo 20 Dirt/Sediment washing off the road into the field by the TB location.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 21 Dirt/Sediment washing off the road into the field by the TB location.

Photo 22 Dirt/Sediment washing off the road into the field by the TB location.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 23 Dirt/Sediment washing off the wellsite into the field.

Photo 24 Dirt/Sediment washing off the road into the field by the wellste.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 25 Dirt/Sediment washing off the wellsite into the field.



Photo 26 Dirt/Sediment washing off the road into the field by the wellsite.