

**GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE**  
**Location #324459**  
**Date: 6/28/2023**



**NW Corner of Location – Photo #04851**



**SW Corner of Location – Photo #04852**

**GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE**  
**Location #324459**  
**Date: 6/28/2023**



**SE Corner of Location – Photo #04853**

**NE Corner of Location – Photo #04854**

**GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE**  
**Location #324459**  
**Date: 6/28/2023**



**Wellhead – Photo #04855**



**Separator – Photo #04860**

# GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE

Location #324459

Date: 6/28/2023



Tank Battery – Photo #04866

Gas Meter – Photo #04878

**GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE**  
**Location #324459**  
**Date: 6/28/2023**



**Storage of Supplies on Location – Photo #04865**



**Wellhead Cellar Full of Water – Photo #04859**

# GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE

Location #324459

Date: 6/28/2023



**Separator Missing Required Information – Photo #04861**



**Anchor not Adequately Marked– Photo #04877**

**GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE**  
**Location #324459**  
**Date: 6/28/2023**



**Anchor not Adequately Marked – Photo #04879**



**Location Lacks Stabilization – Photo #04870**

# GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE

Location #324459

Date: 6/28/2023



**Location Lacks Stabilization – Photo #04869**



**Gully Erosion Transporting Sediment Off Location – Photo #04873**

# GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE

Location #324459

Date: 6/28/2023



**Gully Erosion Transporting Sediment Off Location –  
Photo #04874**



**Erosion From Location Transporting Sediment Into  
Nearby Creek – Photo #04875**

# GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE

Location #324459

Date: 6/28/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #04880**

**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #04881**

# GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE

Location #324459

Date: 6/28/2023



**Unprotected Spoil Piles Near Creek on Lease Road –  
Photo #04883**



**Unprotected Spoil Piles Near Creek on Lease Road –  
Photo #04884**

# GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE

Location #324459

Date: 6/28/2023



**Unprotected Spoil Piles Near Creek on Lease Road –  
Photo #04885**



**Unprotected Spoil Piles Near Creek on Lease Road –  
Photo #04886**