

TEP
Nesbitt
Location # 335387



Tank battery



Separators

TEP
Nesbitt
Location # 335387



Well heads



Stored equipment from recent inspection



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
Nesbitt
Location # 335387



Stored equipment from recent inspection



Stored equipment from previous inspection



TEP
Nesbitt
Location # 335387



Erosion and sediment migration from location choking out vegetation.



Erosion and sediment migration from location choking out vegetation.



TEP
Nesbitt
Location # 335387



**Erosion and sediment migration from location
choking out vegetation.**



**Erosion and sediment migration from location
choking out vegetation.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
Nesbitt
Location # 335387



**Erosion and sediment migration from location
choking out vegetation.**



**Erosion and sediment migration from location
choking out vegetation.**