

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634




Photo 1 – Wellhead



Photo 2 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 3 – Stained Soil at West Side of Gear Box



Photo 4 – Flare and ECD

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 5 – Gas Meter