

Inspection Photos  
Location Name: Strudinger 1-31H  
Location ID: 424744



Photo 1 – NFA Label on Middle Oil Tank

Photo 2 – NFA Label on Water Tank

Inspection Photos  
Location Name: Strudinger 1-31H  
Location ID: 424744



Photo 3 – Tank Battery Sign

Photo 4 – Heater Treater

Inspection Photos  
Location Name: Strudinger 1-31H  
Location ID: 424744



Photo 5 – ECD and Flare



Photo 6 – Wellhead