

Operator: EXTRACTION OIL & GAS INC
Location Name: WENZEL-61S65W 30NWSW
Loc ID: 320612
Inspection: 709400303



Exhibit A



Exhibit B

CA: Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606.c.

CA Resolution: Weeds have been mowed and will be managed according to Rule 606. Area will be monitored and maintained moving forward.

CA: Stormwater erosion on site leading into excavations. Comply with Rule 1002.f. Stormwater Management

CA Resolution: Photos have been provided regarding the erosion control repairs. Location is currently in compliance with Rule 1002.f.