

EAST QUINCY AVENUE




IMAGE COURTESY OF GOOGLE EARTH 2017

**LEGEND**

- SOIL BORING
- IMPACTED SOIL IN-PLACE BOUNDARY
- - - DASHED WHERE INFERRED
- /// ESTIMATED EXTENT OF SOIL NON-COMPLIANT WITH TABLE 915 ORGANIC SOIL STANDARDS

NOTE: ALL INFRASTRUCTURE ON SITE IS FORMER.



**FIGURE 1**  
**TABLE 915 ORGANICS ASSESSMENT MAP**  
**DRAGON COMPRESSOR STATION**  
**NENE SEC 8-T5S-R62W**  
**ARAPAHOE COUNTY, COLORADO**  
**KERR MCGEE GATHERING, LLC**

