



99999999

**OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT**

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- <u>025 - 5198</u>		LEASE NAME: <u>Dune Ridge 5</u>	
LOCATION: <u>SW SW 32 NW-52</u>		OPERATOR: <u>Milinda Brandy</u>	
DATE: <u>11-30-95</u>		INSPECTOR: <u>Binkley</u>	
Insp. Type: <u>SR</u>	Insp. Status: <u>PA</u>	PA: <u>(Y)</u> N	Pass/Fail: <u>P</u> F Viol.: Y <u>(N)</u> NOV: Y <u>(N)</u>

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210)		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)		
<b>Fences</b> (Rule 604.C.(3), 1003.A)	<u>(C)</u>	
<b>Tank Battery Equipment</b> (Rule 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 604)		
<b>General Housekeeping</b> (Rule 603.G)		
<b>Spills (Oil/Water)</b> (Rule 908)		
<b>Bradenhead</b> (Rule 207)		
<b>Drilling Well/Workover</b> (Rule 315)		
<b>Surface Rehabilitation</b> (Rule 317)	<u>grass land</u>	
<b>Miscellaneous</b>	<u>Restored by Les Sessions</u>	

**CORRECTIVE ACTION REQUIRED:**

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in action by the Commission.

White



00220375