

# Inspection Photos

6/28/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 479149

Rio Blanco County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



June 28, 2023



June 28, 2023

**Photo 1:** Photos taken from the Location entrance on the southwest end of the Location. Photos provide an overview of the Location from north to east.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 2:** Signage at Location entrance. 2A permit information not observed on Location.

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479149



**Photo 3:** Photos 3-6 taken from the Cuttings Trench on the south end of the Location. Photos examples showing Operator has improperly placed and buried trash/rubbish/etc... within the cuttings trench.

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479149



**Photo 4:** See comments under photo 3.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 5:** See comments under photo 3.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 6:** See comments under photo 3. Photo also show areas where cuttings material appears to have spilt over the containment berm. Photo also shows trash debris.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 7:** Photos taken from the Cuttings Trench on the south end of the Location. Photos show the containment berm is largely unconsolidated material; BMP has not been installed or maintained in accordance with good engineering practices. Areas of the BMP also appear to have been mixed with cuttings material.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 8:** Photo taken from the southeast end of the Location. Photo shows trash debris, and what appears to be unused materials improperly stored on the surface of the Location.

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479149



**Photo 9:** Photos taken from the southeast end of the Location. Previous inspection observed various spills due to improper materials handling within the southeast areas. Photo shows spills within the material storage area of the Location remain apparent. Photo also shows trash debris on surface of Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479149



**Photo 10:** Photo taken from the east end of the Location. Photo shows unused tarp material, and a bag with apparent staining; stained soils observed beneath bag in photo right. Unused materials/equipment/supplies require removal. Stained soils require cleaning/remediation to Table 915-1 standards.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 11:** Photo shows unlabeled container with unknown fluids observed on the Location. No wildlife protection BMPs in place; no spill prevention or containment BMPs observed. Fluids require removal and proper disposal.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 12:** Photos taken from the east end of the Location. Photo shows what appears to be empty chemical jugs (trash/debris/rubbish) improperly stored on the Location. Photo also show two tanks missing required labeling pursuant to Rule 605.h, and spill prevention/containment BMPs.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 13:** Photos examples showing various other trash/debris/rubbish observed throughout the Location.

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479149



**Photo 14:** Photos examples showing various other trash/debris/rubbish observed throughout the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 15:** Photos examples showing various other trash/debris/rubbish observed along the perimeter of the disturbance area.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



June 28, 2023



June 28, 2023

**Photo 16:** Photos show four (4) porta-john units on the Location; Spill prevention/containment BMPs observed to be missing or insufficient at porta-johns.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 17:** Photos 17-19 example showing tanks on the Location missing required labeling information pursuant to Rule 605.h. Photos also show tanks are missing spill prevention/containment BMPs.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 18:** See comment under photo 18.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 19:** See comment under photo 18.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 20:** Photo example of tank on the Location with required label information including, but not limited to, Operator name, emergency contact number, tank capacity, tank contents, NFPA label, etc... Photos also shows tank is missing spill prevention/containment BMPs.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 21:** Photo taken from the tank battery on the northeast end of the Location. Photo shows signage information has not been posted at the facility, and label information has not been posted on the two tanks.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 22:** Photo example showing barrel observed missing spill prevention/containment BMPs.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 23:** Photos examples showing containers on Location missing spill prevention/containment BMPs.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 24:** Photos 24-26 examples showing additional spills/stained soils observed throughout the Location. See photos

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479149



**Photo 25:** See comments under photo 24.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 26:** Photo shows stained soils from what appears to be a spill at the tank. See comments under photo 12 regarding tank labeling, trash, and spill prevention/containment BMPs.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 27:** Photos 27-28 taken from the topsoil stockpiles on the perimeter of the Location. Photos show Operator has implemented additional BMPs to protect the topsoil stockpiles, and to ensure soils remain properly segregated, and not incorporated as part of stormwater management BMPs for the Location.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 479149



**Photo 28:** See comments under photo 27.