

Inspection Photos
Location Name: KLEIN/B16-99HZ
Location ID: 420631



Photo #1

Klein B15-13D (123-32652) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 5 yds.



Photo #2

Klein B15-13D, B16-98HZ, B16-99HZ Battery site

Abandoned: ALL Equipment Removed