

Inspection Photos
Location Name: KLEIN/B16-99HZ
Location ID: 420631



Photo #1
Klein B16-99HZ (123-32650) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 5 yds.



Photo #2
Klein B15-13D, B16-98HZ, B16-99HZ Battery site
Abandoned: ALL Equipment Removed