

Inspection Photos
Location Name: KBL 02N-63-19 Tank Battery
Location ID: 471229



Location



Inspection Photos
Location Name: KBL 02N-63-19 Tank Battery
Location ID: 471229



Missing bird protector



Unmarked Riser

Inspection Photos
Location Name: KBL 02N-63-19 Tank Battery
Location ID: 471229



Unmarked Riser



Unmarked Riser

Inspection Photos
Location Name: KBL 02N-63-19 Tank Battery
Location ID: 471229



Unmarked Riser



Compressor