

# Inspection Photos

API: 061-06515

Operator: EOG RESOURCES INC

Inspection Date: 7/6/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06515 - Date: 7/6/2023

## Inspection Photos



**Photo 1.** Center of the location facing north. Perennial vegetation has uniformly established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06515 - Date: 7/6/2023

## Inspection Photos



**Photo 2.** There are four corner posts that remain around the location that need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06515 - Date: 7/6/2023