

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 1 – Generator Area – WEEDS



Photo 2 – Generator Area – WEEDS

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 3 – Generator – Unmarked Riser

Photo 4 – WEEDS

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 5 – Containment – Wildlife Netting missing and Debris inside Containment



Photo 6 – Trash at Flare

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 7 – WEEDS



Photo 8 – ECD, Gas Meter and Heater Treater

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 9 – Flare Area



Photo 10 – Heater Treater

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 11 – Propane Tank




Photo 12 – Unmarked Risers

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 13 – WEEDS East of Tanks



Photo 14 – WEEDS

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 15 – WEEDS looking North



Photo 16 – WEEDS in Interim Reclamation Area

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



COGCC
40.63839, -104.27631, 4945.6ft
06/27/2023 12:26:08

Photo 17 – WEEDS looking South



COGCC
40.63831, -104.2763, 4942.8ft
06/27/2023 12:26:18

Photo 18 – Tank Battery Signs

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 19 – WEED debris at Stairs



Photo 20 – WEEDS looking West in Interim Reclamation Area