

Final Reclamation Inspection

June 30, 2023

Operator: NOBLE ENERGY INC - #100322

Location ID: 322698

Inspection Document #: 697504739

Weld County, CO

NWSW Section 8 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: RYDGREN #8-1
Location ID: 322698



Photo 1. Photo taken from the well location, facing Southeast. Photo illustrates the well location is not reflective of reference areas. Well location consists mostly of annual weeds, while the reference area consists mostly of a perennial grass, Crested wheatgrass.



Photo 2. Reference photo taken from the well location, facing Southwest. Photo illustrates a field of Crested wheatgrass.



Inspection Photos
Location Name: RYDGREN #8-1
Location ID: 322698



Photo 3. Photo taken from the northern portion of the associated tank battery location, facing East. Photo illustrates the northern portion of the tank battery consists mostly of annual weeds.



Photo 4. Photo taken from the southern portion of the associated tank battery location, facing South. Photo illustrates a mix of perennial grasses and some annual weeds. The perennial grasses are not reflective of the reference perennial grass, Crested wheatgrass.

Note- utility services traveled into the southern portion of the tank battery for maintenance work.

