

# Interim Reclamation and Stormwater Inspection

June 30, 2023

Operator: NOBLE ENERGY INC - #100322

Location ID: 332789

Inspection Document #: 697504741

Weld County, CO

NENE Section 7 T4N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Dietrich C08-30D Pad  
Location ID: 332789



**Photo 1.** Photo taken from the well location, facing East. Photo illustrates Operator has plugged and abandoned 5 of the 6 wells.



**Photo 2.** Photo taken from the associated offsite tank battery, facing Southwest. Photo illustrates gully erosion without sufficient stormwater BMPs. Also, the culvert is in need of repair.



Inspection Photos  
Location Name: Dietrich C08-30D Pad  
Location ID: 332789



**Photo 3.** Photo taken from the associated offsite tank battery, facing South. See comments under Photo 2.