

Inspection Photos

Location Name: MorningStar Schumacher 32-6 13-2

Location ID: API 007-06209



Photo #1. Overview of the well location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: MorningStar Schumacher 32-6 13-2
Location ID: API 007-06209



Photo #2. View of the 13-2 wellhead assembly.

Inspection Photos
Location Name: MorningStar Schumacher 32-6 13-2
Location ID: API 007-06209



Photo #3. View of the 13-1 wellhead assembly.

Inspection Photos
Location Name: MorningStar Schumacher 32-6 13-2
Location ID: API 007-06209



Photo #4. View of unused equipment stored on the well location.