

Interim Reclamation and Stormwater Inspection

July 5, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 423325

Inspection Document #: 697504751

Weld County, CO

SENE Section 2 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bestway/Pad
Location ID: 423325



Photo 1. COGCC GISOnline aerial imagery from 2021 illustrates the location overview in relation to surface features, including Waters of the State to the north-northeast.

Inspection Photos
Location Name: Bestway/Pad
Location ID: 423325



Photo 2. Photo taken from the southwestern location, facing North. Cut slopes have been seeded and are in-process of perennial vegetative establishment.



Photo 3. Photo taken from the southwestern location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: Bestway/Pad
Location ID: 423325



Photo 4. Photo taken from the eastern location. Photo illustrates stormwater BMPs have been installed but are in need of repair. Gully erosion is exposing an unknown line.



Photo 5. Photo taken from the northeastern location, facing South. Photo illustrates a stormwater BMP in need of repair, as sediment has discharged off location and beyond the BMP. Refer to Photo 6.



Inspection Photos
Location Name: Bestway/Pad
Location ID: 423325



Photo 6. Photo taken from the northeastern location, facing Northeast. Photo illustrates sediment discharge from location.