

Final Reclamation Inspection

July 5, 2023

Operator: NOBLE ENERGY INC - #100322

Location ID: 332296

Inspection Document #: 697504761

Weld County, CO

SWSW Section 34 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WILLIAMS I-66N66W 34SWSW
Location ID: 332296



Photo 1. Google Earth aerial imagery taken 10/7/2004 illustrates pre-disturbance conditions for the tank battery location. Photo illustrates the tank battery was previously vegetated.



Inspection Photos
Location Name: WILLIAMS I-66N66W 34SWSW
Location ID: 332296



Photo 2. Google Earth aerial imagery taken 6/19/2014 illustrates the tank battery location during active operations.



Inspection Photos

Location Name: WILLIAMS I-66N66W 34SWSW

Location ID: 332296



Photo 3. Photo taken from the associated offsite tank battery, facing West. Photo illustrates all the equipment has been removed and the surface owner appears to be using the area for livestock operations.



Photo 4. Photo taken from the associated offsite tank battery, facing East. See comments under Photo 3.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 697504761