

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



Photo # 2759 From entrance to location



Photo # 2760 From entrance to location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



Photo # 2761 Location



Photo # 2762 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



Photo # 2763 Location



Photo # 2764 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618




Photo # 2022 From inspection 708900094 conducted on 03/08/2023 Containment needs maintenance

Photo # 2773 Containment needs maintenance

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



**Photo # 2023 From inspection 708900094 conducted on 03/08/2023 Containment needs maintenance**

**Photo # 2774 Containment needs maintenance**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



**Photo # 2769 Containment liner needs maintenance**



**Photo # 2772 Containment liner needs maintenance**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



**Photo # 2765 Multiple signs have some illegible info & 1 sign has incorrect operator name.**



**Photo # 2767 Weeds in secondary containment**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



Photo # 2768 Debris



Photo # 2771 Unused equipment

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



Photo # 2778 Debris & Unused equipment/Supplies



Photo # 2766 Unused equipment/Supplies

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



Photo # 2783 Unmarked deadman (N/NW edge of location)



Photo # 2784 Same unmarked deadman from different view

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



**Photo # 2785 Same unmarked deadman from a different angle**