

Inspection Photos

API: 099-06909

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 7/11/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06909 | Date: 7/11/2023

Inspection Photos



Photo 1. Facing northeast toward the offsite tank battery there is no sign posted at the tank battery which is off site from the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06909 | Date: 7/11/2023

Inspection Photos



Photo 2. Facing toward the tank which is labeled as water. It appears crude oil has leaked out from the top. Additionally there is no secondary containment around the tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06909 | Date: 7/11/2023

Inspection Photos



Photo 3. There is oil stained soils at the tank that need to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06909 | Date: 7/11/2023

Inspection Photos



Photo 4. There is well sign posted at the wellhead. The well is a distance away from the tank battery and an addition sign should be posted at the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06909 | Date: 7/11/2023