

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/06/2023

Submitted Date:

07/06/2023

Document Number:

696305079

FIELD INSPECTION FORM
 Loc ID: 442024 Inspector Name: PETRIE, ERICA On-Site Inspection: ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10518

Name of Operator: CONFLUENCE DJ LLC

Address: 1125 17TH STREET #1550

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

45 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Gale, Justin		jpgale@confluencelp.com	All Inspections
Weitzel, Bob		rweitzel@confluencelp.com	All Inspections
Rothe, Brittany		brothe@confluencelp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442023	WELL	TA	03/20/2023	OW	123-41614	State Seventy Holes J-18	TA
456221	WELL	WO	03/01/2023	LO	123-47438	Flaherty 13-11-3	WO
456222	WELL	WO	03/01/2023	LO	123-47439	Flaherty 13-8-3	WO
456223	WELL	WO	03/01/2023	LO	123-47440	Middlepark 18-4-4L	WO
456224	WELL	WO	03/01/2023	LO	123-47441	Middlepark 18-9-2	WO
456225	WELL	WO	03/01/2023	LO	123-47442	Middlepark 18-3-2L	WO
456227	WELL	PR	12/01/2022	OW	123-47444	Middlepark 18-21-3L	PR
456228	WELL	WO	03/01/2023	LO	123-47445	Flaherty 13-12-1	WO
456229	WELL	PR	12/01/2022	OW	123-47446	Middlepark 18-5-4L	PR
456230	WELL	WO	03/01/2023	LO	123-47447	Flaherty 13-3-4	WO
456231	WELL	WO	03/01/2023	LO	123-47448	Flaherty 13-6-1	WO
456232	WELL	WO	03/01/2023	LO	123-47449	Flaherty 13-5-3	WO
456233	WELL	WO	03/01/2023	LO	123-47450	Middlepark 18-4-1L	WO
456234	WELL	WO	03/01/2023	LO	123-47451	Flaherty 13-4-4	WO
456235	WELL	WO	03/01/2023	LO	123-47452	Middlepark 18-11-1L	WO
456236	WELL	WO	03/01/2023	LO	123-47453	Middlepark 18-7-1L	WO
456237	WELL	WO	03/01/2023	LO	123-47454	Middlepark 18-2-3L	WO
456238	WELL	WO	03/01/2023	LO	123-47455	Middlepark 18-12-2L	WO
456239	WELL	WO	03/01/2023	LO	123-47456	Flaherty 13-13-2	WO
456240	WELL	WO	03/01/2023	LO	123-47457	Middlepark 18-6-2L	WO

456241	WELL	WO	03/01/2023	LO	123-47458	Flaherty 13-5-4	WO
456242	WELL	WO	03/01/2023	LO	123-47459	Middlepark 18-8-3L	WO
456243	WELL	WO	03/01/2023	LO	123-47460	Middlepark 18-5-3L	WO
456244	WELL	WO	03/01/2023	LO	123-47461	Flaherty 13-7-2	WO
456245	WELL	WO	03/01/2023	LO	123-47462	Flaherty 13-14-3	WO

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash on North Side of Location; see photos		
Corrective Action:	Comply with Rule 606	Date:	07/21/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: VRU	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:		Date:	

Type: Pig Station	# 2		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	#		
Comment:	22 - WO - Wellheads Drilled, Not yet Complete		
Corrective Action:			Date:
Type: Bradenhead	#		
Comment:	25 Bradenheads - Appear to be plumbed to surface		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Automation and Electrical Equipment		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	TA - State Severy Holes J-18 Wellhead		
Corrective Action:			Date:
Type: VRT	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	500 BBLs	STEEL AST		,	
Comment:	East Tank Battery					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Shares berm with the Crude Oil Tank						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	500 BBLs	STEEL AST		40.307120,-104.371120	
Comment: East Tank Battery						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	500 BBLs	STEEL AST		,	
Comment: West Tank Battery						
Corrective Action:					Date:	
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Shares berm with the Crude Oil Tanks						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	6	500 BBLs	STEEL AST		40.306250,-104.372700	
Comment: West Tank Battery						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 442023 Type: WELL API Number: 123-41614 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: TA - MIT 10.08.2020

Corrective Action: _____ Date: _____

Facility ID: 456221 Type: WELL API Number: 123-47438 Status: WO Insp. Status: WO

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456222 Type: WELL API Number: 123-47439 Status: WO Insp. Status: WO

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456223 Type: WELL API Number: 123-47440 Status: WO Insp. Status: WO

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456224 Type: WELL API Number: 123-47441 Status: WO Insp. Status: WO

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456225 Type: WELL API Number: 123-47442 Status: WO Insp. Status: WO

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456227 Type: WELL API Number: 123-47444 Status: PR Insp. Status: PR

<u>Producing Well</u>				
Comment:	PR			
Corrective Action:		Date:		
Facility ID:	456228	Type:	WELL	API Number: 123-47445 Status: WO Insp. Status: WO
<u>Idle Well</u>				
Purpose:	<input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: _____	
Comment:	WO - Well has been Drilled; Waiting Completion			
Corrective Action:		Date:		
Facility ID:	456229	Type:	WELL	API Number: 123-47446 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	PR			
Corrective Action:		Date:		
Facility ID:	456230	Type:	WELL	API Number: 123-47447 Status: WO Insp. Status: WO
<u>Idle Well</u>				
Purpose:	<input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: _____	
Comment:	WO - Well has been Drilled; Waiting Completion			
Corrective Action:		Date:		
Facility ID:	456231	Type:	WELL	API Number: 123-47448 Status: WO Insp. Status: WO
<u>Idle Well</u>				
Purpose:	<input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: _____	
Comment:	WO - Well has been Drilled; Waiting Completion			
Corrective Action:		Date:		
Facility ID:	456232	Type:	WELL	API Number: 123-47449 Status: WO Insp. Status: WO
<u>Idle Well</u>				
Purpose:	<input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: _____	
Comment:	WO - Well has been Drilled; Waiting Completion			
Corrective Action:		Date:		
Facility ID:	456233	Type:	WELL	API Number: 123-47450 Status: WO Insp. Status: WO
<u>Idle Well</u>				
Purpose:	<input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned		Reminder: _____	
Comment:	WO - Well has been Drilled; Waiting Completion			
Corrective Action:		Date:		
Facility ID:	456234	Type:	WELL	API Number: 123-47451 Status: WO Insp. Status: WO

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456235 Type: WELL API Number: 123-47452 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456236 Type: WELL API Number: 123-47453 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456237 Type: WELL API Number: 123-47454 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456238 Type: WELL API Number: 123-47455 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456239 Type: WELL API Number: 123-47456 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456240 Type: WELL API Number: 123-47457 Status: WO Insp. Status: WO

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456241 Type: WELL API Number: 123-47458 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456242 Type: WELL API Number: 123-47459 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456243 Type: WELL API Number: 123-47460 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456244 Type: WELL API Number: 123-47461 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Facility ID: 456245 Type: WELL API Number: 123-47462 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: WO - Well has been Drilled; Waiting Completion

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Trash on North Side of Location	petrie	07/06/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403455694	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6171741
696305080	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6171735